



Chief Scrutineer's Bulletin - #5 2017

Attention Team Managers

Re: Completing the Team Manager Scrutineering Check List for Round 4

Conscientious Team Managers are concerned about not being able to fully comply with Item 9 of the TMSCL for Round 4 which asks for every rider to have done a Roll-Over Test.

In the Vehicle Specifications, this is only a recommendation and has only just been put into the TMSCL.

During discussion with the Team Manager, Scrutineers will be looking for Teams to have made an effort to give their riders this training. This will satisfy the tick box. Riders may have had sufficient on-track experience.

It is much more important that Item 1 is met, so that every rider goes onto the track with their seat belt properly adjusted and their helmet fitting correctly.

Rob Spurling
AIPP Chief Scrutineer
24 July 2017